

# RADIATION SURVEY WORKSHEET

eXaminer Radiation Survey Information


Airport: <b>T.F Green Airport</b>	Scanner Location: <b>Baggage Handling Room</b>	Case#: <b>PVD-C357803</b>
Personnel Performing Radiation Survey: <span style="background-color: black; color: black;">XXXXXXXXXX</span>		Date Survey Performed: <b>3/24/2010</b>
Scanner Serial Number: <b>6750</b>	Entrance Tunnel Serial Number: <b>1106</b>	Exit Tunnel Serial Number: <b>1085-1B</b>
High Reading: <b>35</b>	Average Reading: <b>14.01</b>	Min. Reading: <b>4</b>
High Reading: <b>112</b>	Average Reading: <b>26.41</b>	Min. Reading: <b>6</b>
High Reading: <b>71</b>	Average Reading: <b>22.60</b>	Min. Reading: <b>8</b>
<b>Good</b>	<b>Good</b>	<b>Good</b>
Radiation Meter: Type Meter: <b>451P</b>	Meter Serial Number: <b>6230</b>	Calibration Due Date: <b>February 1, 2012</b>

N  
O  
T  
E  
S

<b>Complete Radiation Survey (CRS)</b>	<b>Record Voltage and Beam Current here:</b>								
<p><b>Rename this Document before starting the Survey to:</b></p> <p style="text-align: center;"><b>PVD-CRS-24MAR2010-6750</b></p>	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;"><b>Voltage:</b> <b>165</b> KV</td> <td style="width: 30%;"><b>Beam Current:</b> <b>10.0</b> mA</td> </tr> <tr> <td><b>Maximum Safe Readings</b></td> <td></td> </tr> <tr> <td style="text-align: center;"><b>Scanner</b> 350</td> <td style="text-align: center;"><b>Tunnels</b> 350</td> </tr> <tr> <td style="text-align: center;"><b>Curtains</b> 350</td> <td></td> </tr> </table>	<b>Voltage:</b> <b>165</b> KV	<b>Beam Current:</b> <b>10.0</b> mA	<b>Maximum Safe Readings</b>		<b>Scanner</b> 350	<b>Tunnels</b> 350	<b>Curtains</b> 350	
	<b>Voltage:</b> <b>165</b> KV	<b>Beam Current:</b> <b>10.0</b> mA							
<b>Maximum Safe Readings</b>									
<b>Scanner</b> 350	<b>Tunnels</b> 350								
<b>Curtains</b> 350									

Step:	Procedure	Expected results
1.	Set Up: Obtain Inovision Ion Chamber Survey Meter and in an area away from the scanners, turn on the meter by pressing the On-Off key. Wait approx. 4 minutes for the meter to run through the initialization procedure.	The GUI will be visible and will indicate Standby. After the radiation meter initialization procedure is complete the meter will be reading less than 20 $\mu$ R/hr and the meter will be ready for use.
2.	The scanner will be in Standby. Change the conveyor switch on the scanner to Stop. Change the exit tunnel conveyor switch to Off to stop the conveyor.	Both conveyors should be stopped.
3.	On the GUI dropdown screen, select diagnostic, followed by Radiation Survey. A radiation survey window will appear. Click "Turn On" button to turn x-rays on. Turn on x-rays prompt will say "Place survey bag on belt". Place IQTK bag on Entry Conveyor Belt.	A window indicating "Radiation Survey" will appear.
4.	When "Bag in survey position" appears, go to the FCC monitor and select "2" then <Enter>, verify and record the voltage and current in the displayed on the FCC screen in the planks provided above.	The high voltage is between <b>144KV</b> and <b>176KV</b> . The current is between <b>8.8mA</b> and <b>10.6mA</b> and the scanner X-ray indicator lights are on.
5.	Survey one of the areas indicated by the boxes in Appendix A2. Record the highest reading within the area. Repeat the process until all areas are surveyed and readings are recorded.	As the survey is conducted, the radiation meter indicates the degree of radiation emission.
6.	Review all radiation data sheets for high readings.	Readings shall not exceed 350 uR/hr in any box.
7.	After radiation survey is complete, click on "Start Conveyor" button on the GUI. Click the "Turn Off" button to turn off x-rays. Next click "Done". The IQTK bag will eject from exit tunnel. EDAC will reboot.	IQTK bag is ejected and scanner reboots.
7.	Visually inspect the entrance and exit of the system for X-ray caution hazard signs.	X-ray hazard signs reading "Do not insert any part of the body when system is energized" are posted at entrance and exit of system.
9.	<a href="#">Fill out the eXaminer radiation stickers and place on the eXaminer in accordance with Examiner Technical Bulletin ex253.</a>	Readings shall not exceed 350 uR/hr in any box.

# RADIATION SURVEY WORKSHEET




Top View			
Scattered Radiation Measurement Points Worksheet			No PROBLEM
Record highest reading per panel		μR/Hr	
1	Exit Conveyor Top Panel	54	
2	Exit Conveyor Top Panel	71	
3	Exit Conveyor Top Panel	19	
4	Scanner Conveyor Top Panel	6	
5	Scanner Conveyor Top Panel	16	
6	Scanner Conveyor Top Panel	19	
7	Entrance Conveyor Top Panel	13	
8	Entrance Conveyor Top Panel	33	
9	Entrance Conveyor Top Panel	26	

GOOD

Highest Reading	71
Average Reading	29
Lowest Reading	6

# RADIATION SURVEY WORKSHEET

## SIDE PROFILE VIEW (OPPOSITE AC)




SYSTEM - SIDE PROFILE VIEW (Opposite AC Side)		
Scattered Radiation Measurement Points Worksheet		
Record highest reading per panel		$\mu\text{R}/\text{Hr}$
1	Entrance Conveyor Panel	15
2	Entrance Conveyor Panel	12
3	Entrance Conveyor Panel	20
4	Entrance Conveyor Panel	3
5	Entrance Conveyor / Scanner Panel	4
6	Upper Scanner Panel	15
7	Middle Scanner Panel	4
8	Lower Scanner Panel	13
9	Upper Scanner Panel	9
10	Middle Scanner Panel	9
11	Lower Scanner Panel	4
12	Exit Conveyor / Scanner Panel	12
13	Exit Conveyor Panel	12
14	Exit Conveyor Panel	46
15	Exit Conveyor Panel	12
16	Exit Conveyor Panel	10

GOOD

Highest Reading	46
Average Reading	13
Low Reading	3

# RADIATION SURVEY WORKSHEET




SYSTEM - SIDE PROFILE VIEW ( AC Side)			
Scattered Radiation Measurement Points Worksheet			No PROBLEM
Record highest reading per panel		µR/Hr	
1	Exit Conveyor Panel	12	
2	Exit Conveyor Panel	14	
3	Exit Conveyor Panel	9	
4	Exit Conveyor Panel	8	
5	Exit Conveyor / Scanner Panel	20	
6	Upper Scanner Pane	23	
7	Middle Scanner Panel	35	
8	Lower Scanner Panel	9	
9	Upper Scanner Panel	15	
10	Middle Scanner Panel	14	
11	Lower Scanner Panel	12	
12	Entrance Conveyor / Scanner Panel	6	
13	Entrance Conveyor Panel	15	
14	Entrance Conveyor Panel	10	

GOOD


Highest Reading	35
Average Reading	14
Low Reading	6

# RADIATION SURVEY WORKSHEET

## SYSTEM - FACES (End Views)



eXaminer entrance



eXaminer exit

SYSTEM - FACES (End Views)			
Scattered Radiation Measurement Points Worksheet			
Record highest reading per panel		$\mu\text{R}/\text{Hr}$	No PROBLEM
1	Scanner Panel	6	
2	Scanner Top Panel	23	
3	Scanner Panel	10	
4	Belt Entrance	112	
5	Entrance Lower Panel	15	
6	Belt Lower Facia Cover Entrance	52	
7	Scanner Panel	13	
8	Scanner Top Panel	30	
9	Scanner Panel	6	
10	Belt Exit	9	
11	Exit Lower Panel	16	
12	Belt Lower Facia Cover Exit	10	

GOOD

Highest Reading	112
Average Reading	25
Low Reading	6