The information in this report is required by 14 CRF 108.17 & 129.26. Failure to report may result in a civil penalty not to exceed $1000.00 for each such violation. (Federal Aviation Act of 1958, Section 901)

Department of Transportation Federal Aviation Administration	X-RAY SYSTEM RADIATION LEAKAGE REPORT (BAGGAGE INSPECTION) (Require by 14 CRF 108.17, 14 CRF 129.26)	FIELD TEST SERIAL NO. 11-7 T	Form Approved OMB No. 2120-0098

AA	1.1 Name and Address of Facility and Specific Location of X-ray System	Name of Facility (18.80): El Paso International Airport	FDA Region: Texas	St. No. N.R. or Airline/Airport (10.80): 6701 Convair Rd.
CC		City (10.73): El Paso	State Code: TX	Zip Code: 79925
DD		Room No. or Other Location of System (10.32): Checkpoint Lane 2	Person Interview (33.34): [redacted]	Telephone No.: [redacted]
		Certification Label Present: Yes	Instruments: (type and serial number) Inovision	Model: 451P Serial No.: 0482
01	1.2 Manufacture And Product ID	A. Manufacture (Responsible Firm): Rapiscan Security Products	B. OHU46	C. System Model No. and/or Name: Rapiscan 520B TRX X-Ray System
		D. Unique I.D.: 115vac 60hz	E. System Serial No.: 7021106	
		F. Date of Manufacture Mo. 03 Yr. 2002	1.4 Operator Instructions Available: Yes	1.5 Maintenance Schedule Available
	2.0 Warning Labels Indicators	2.1 Warning Label Present at Controls Stating: "Caution: X-Rays Produced When Energized" Yes	2.2 Warning Labels Present at Ports Stating: "Caution: Do Not Insert Any Part of the Body When System Is Energized, X-Ray Hazard" Yes	2.3 Two Indicators Labeled "X-Ray On" Present at Controls (One May Be Labeled "mA Meter") Yes
02		2.4 At Least One Indicator, X-Ray Marked "X-Ray On", Visible from Each Port, Door, And Access Panel Yes	3.0 Interlocks	3.1 "Captured Key" Control Yes
	3.2 Door Safety Interlocks	A. Minimum Number of Interlocks Visible At Any One Door	3.3 Prevention of X-Radiation By Interlocks	A. All Doors and Access Panels That Were Tested Prevent Generation of X-Radiation
		B. At Least One Interlock Dependent on No Moving Part Except Door		B. Use of X-Ray Control Necessary to Resume Operation Following Interruption
	4.0 Ports and/or Apertures	4.1 Some Part of the Body Can Be Inserted Through a Port Into The Primary Beam No		4.2 Some Part of the Body Can Be Inserted Into the Aperture No
	6.0 Baggage Inspection Systems	6.1 Means Provided to Ensure Operator Presence at the Control Area Yes		6.2 Means Provided to Operator for Terminating Exposures of Greater than One-Half Second and Preventing Yes
03	7.0 Leakage Radiation	Specific Test Procedure Used 04	7.1 Scatter Block Description: Pelican 1400 case for 451P meter	
05	7.2 Technical Factures	140 kVp	.700 mA	

7.3 Location Exposure Levels	Non-Continuously Activated Systems Only Number of Exposures Initiated		Location Exposure Levels	Non-Continuously Activated Systems Only Number of Exposures Initiated
.061 mR/hr	Exp	06	.044 mR/hr	exp
.052 mR/hr	Exp		.043 mR/hr	exp
.050 mR/hr	exp		.042 mR/hr	exp
.046 mR/hr	exp		.035 mR/hr	exp

07	Reasonable Number of Exposures That May Be Initiated In One Hour	OR	Duty Cycle of System Indicated As a Percentage of One Hour 100%
08	8.0 Additional Information 8.1 1.59		
09	8.2		
10	8.3		
11	8.4		
12	8.5		
13	Surveyor Information: [redacted] (Print: L, F, MI) [redacted]	Date of Survey: 03-26-09	Surveying Agency Code

Remarks:

FAA Form 185-17 (6-81)

EQ: 51828
WO: 2148902
Semi-Annual PM

FAA HQ