Smiths Detection

Field Radiation Survey Sheet

WO# 3768084

SECTION	PART I – GENERAL PROCEDURE INFORMATION				
A "PRE-TEST INFORMATION"	NAME AND ADDRESS OF FACILITY OR AIRPORT AND SPECIFIC LOCATION OF X-RAY SYSTEM				
	NAME OF FACILITY	Denver International Airport			
	Is this Facility Operated Exclusively by the Federal Government?		☐ YES	☑ NO	☒ UNCLASS [redacted] 3/15/11
	ADDRESS (Street No., Rural Rt., or Airline and Airport)	8400 Peña Blvd.			
	CITY	Denver	STATE: CO	ZIP CODE: 80249	
	ROOM NO. or OTHER LOCATION	A Security Lane 4	CONTACT PERSON	[redacted]	
	PHONE NO.	[redacted]	FAX NO.		
	MANUFACTURER	Smith Detection	MODEL NO.	HS 6040 ATIX	
	DATE OF MFR.	November 2007	SERIAL NO.	75636	
	MFR. CERTIFICATION LABEL ATTACHED	☑ YES ☐ NO			
B "CABINET X-RAY CLASSIFICATION"	CLASSIFICATION OF CABINET X-RAY SYSTEM				
	☑ Baggage Inspection	☐ Special Purpose	☐ General Purpose	☐ Other	
	Describe Other:				
C "POSTINGS & INSTRUCTIONS"	POSTING & INSTRUCTION VERIFICATION (Not Applicable for Facilities Operated Exclusively by the Federal Government)				
	☑ State "Notice to Employees" Document Posted	☑ Operators Instruction Manual on Location		☒ N/A [redacted] 3/15/11	
	☑ Certificate of X-ray Machine Registration on Location	☑ Cabinet X-Ray Machine Maintenance Schedule Available			
D "WARNING LIGHTS & INDICATORS"	WARNING LIGHT TO INDICATOR VERIFICATION				
	Warning Label Present at Controls Stating: "Caution: X-Rays Produced When Energized"			☑ YES	☐ NO
	Warning Labels Present at Ports Stating "Caution: Do Not Insert Any Part of the Body When System is Energized, X-Ray Hazard"			☑ YES	☐ NO
	Two Indicators Labeled "X-Ray ON" Present at Controls			☑ YES	☐ NO
	At Least One Indicator, Marked "X-Ray ON", is Visible from Each Port, Door, and Access Panel			☑ YES	☐ NO
E "INTERLOCKS"	INTERLOCK VERIFICATION TEST				
	The Key for the Key Actuated Control Cannot be removed in Any Mode that Allows X-Ray Generation			☑ YES	☐ NO
	All Doors and Access Panels that were Tested Prevent Generation of X-Rays			☑ YES	☐ NO ☒ N/A [redacted] 3/15/11
	The Use of the ON Control is Necessary to Resume Operation of X-Rays Following Interruption of X-Ray Generation			☑ YES	☐ NO
F "PORTS AND APERTURES"	ACCESS TO PORTS AND APERTURES				
	Some Part of the Body Can Be Inserted Through A "Port" Into the Primary Beam			☐ YES	☑ NO
	Some Part of the Body Can Be Inserted Through An "Aperture"			☐ YES ☐ NO	☑ N/A
G "BAGGAGE INSPECTION UNITS"	BAGGAGE INSPECTION UNIT CHECKS ONLY				
	Means Provided to Ensure Operator Presence at the Control Area which Permits Surveillance of All Ports and Doors During X-Ray Generation			☑ YES	☐ NO
	Means Provided to the Operator for Terminating Exposures of Greater Than One-Half Second and Preventing Additional Exposures of Less Than One-Half Second			☑ YES	☐ NO

WO 3768084
EQ 57033
RCS ADHOC TSA
DEN

Form # 002.SerFRSSHF
Revision Date 03/11/2008

Smiths Detection

Field Radiation Survey Sheet

SECTION	PART II - SPECIFIC PROCEDURE INFORMATION
H "LEAKAGE RADIATION"	LEAKAGE RADIATION - SPECIFIC TEST PROCEDURE # 01

Scattering Body Description: 8 rems

☐ Lucite ☑ Paper ☐ Other

Describe Other:

X-Ray Machine Settings: See Comments | kV: Sec I | mA: Sec I

Background: 8 uR/hr

Radiation Survey Instrument Used | Make/Model Number: Inovision 451P | Serial Number: 475 | Calibration Date Due: 9-16-11

Survey Location Description	Survey Point	External Surface Exposure Rates (uR/hr)		Internal Exposure (mR) "Optional"		Comments
Ent. Tunnel	1	29	uR/hr		mR	
PAX Ent. End	2	27	uR/hr		mR	
OPER Ent. End	3	20	uR/hr		mR	
Exit Tunnel	4	47	uR/hr		mR	
PAX Exit End	5	23	uR/hr		mR	
OPER Exit End	6	21	uR/hr		mR	
OPER Small	7	22	uR/hr		mR	
OPER Center	8	24	uR/hr		mR	
OPER Large	9	24	uR/hr		mR	
PAX Small	10	25	uR/hr		mR	
PAX Center	11	27	uR/hr		mR	
PAX Large	12	22	uR/hr		mR	
Top	13	21	uR/hr		mR	

Highest External Surface Exposure Rate Reading: 47 uR/hr | Location Description: Exit tunnel

All External Surface Exposure Rate Readings Are Less Than 500 uR/hr (0.5 mR/hr) IAW 21 CFR 1020.40: ☑ YES ☐ NO

I "ADDITIONAL INFORMATION"	ADDITIONAL INFORMATION

Overall Condition of Cabinet X-Ray Unit	☑ SAT	☐ UNSAT *	* Describe UNSAT Condition
Condition of Lead Curtains	☑ SAT	☐ UNSAT *	* Describe UNSAT Condition

Other Comments, Recommendations, Corrections, or Problems Encountered

	KV	mA
A	155	481
B	166	526
C	151	453
D	160	480

Average Internal Dose .78 mRem/hour

E (B) - "SECTION E - NO DOORS/INTERLOCKS APPLICABLE" [redacted] 3/15/11

SURVEYOR'S NAME (Print: Last, First, Middle Int. [redacted]

SURVEYOR'S SIGNATURE [redacted]

DATE OF SURVEY AND INSPECTION: 3-8-2011

Form # 002.SerFRSSHF
Revision Date 03/11/2008