Smiths Detection

Field Radiation Survey Sheet

WO# 3738879

SECTION	PART I - GENERAL PROCEDURE INFORMATION				
A "PRE-TEST INFORMATION"	NAME AND ADDRESS OF FACILITY ON AIRPORT AND SPECIFIC LOCATION OF X-RAY SYSTEM				
	NAME OF FACILITY	Denver International Airport			
	Is this Facility Operated Exclusively by the Federal Government?		☐ YES	☑ ~~NO~~	☒ UNKNOWN [redacted] 3-16-11
	ADDRESS (Street No., Rural Rt., or Airline and Airport)	8400 Peña Blvd.			
	CITY	Denver	STATE: CO	ZIP CODE: 80249	
	ROOM NO. or OTHER LOCATION	North Check Pt Ln 2	CONTACT PERSON	Paula Monahan	
	PHONE NO.	303-342-4252	FAX NO.		
	MANUFACTURER	Smith Detection	MODEL NO.	HS 6040 ATIX	
	DATE OF MFR.	FEB 2008	SERIAL NO.	76972	
	MFR. CERTIFICATION LABEL ATTACHED	☑ YES ☐ NO			
B "CABINET X-RAY CLASSIFICATION"	CLASSIFICATION OF CABINET X-RAY SYSTEM				
	☑ Baggage Inspection	☐ Special Purpose	☐ General Purpose	☐ Other	
				Describe Other:	
C "POSTINGS & INSTRUCTIONS"	POSTING & INSTRUCTION VERIFICATION (Not Applicable for Facilities Operated Exclusively by the Federal Government)				
	☑ State "Notice to Employees" Document Posted		☑ Operators Instruction Manual on Location		☒ N/A [redacted] 3-16-11
	☑ Certificate of X-ray Machine Registration on Location		☑ Cabinet X-Ray Machine Maintenance Schedule Available		
D "WARNING LIGHTS & INDICATORS"	WARNING LIGHTS & INDICATOR VERIFICATION				
	Warning Label Present at Controls Stating: "Caution: X-Rays Produced When Energized"			☑ YES	☐ NO
	Warning Labels Present at Ports Stating ""Caution: Do Not Insert Any Part of the Body When System is Energized, X-Ray Hazard"			☑ YES	☐ NO
	Two Indicators Labeled "X-Ray ON" Present at Controls			☑ YES	☐ NO
	At Least One Indicator, Marked "X-Ray ON", is Visible from Each Port, Door, and Access Panel			☑ YES	☐ NO
E "INTERLOCKS"	INTERLOCK VERIFICATION TEST				
	The Key for the Key Actuated Control Cannot be removed in Any Mode that Allows X-Ray Generation			☑ YES	☐ NO
	All Doors and Access Panels that were Tested Prevent Generation of X-Rays			☑ YES	☐ NO ☒ N/A [redacted] 3-16-11
	The Use of the ON Control is Necessary to Resume Operation of X-Rays Following Interruption of X-Ray Generation			☑ YES	☐ NO
F "PORTS AND APERTURES"	ACCESS TO PORTS AND APERTURES				
	Some Part of the Body Can Be Inserted Through A "Port" Into the Primary Beam			☐ YES	☑ NO
	Some Part of the Body Can Be Inserted Through An "Aperture"			☐ YES ☐ NO	☑ N/A
G "BAGGAGE INSPECTION UNITS"	BAGGAGE INSPECTION UNIT CHECKS ONLY				
	Means Provided to Ensure Operator Presence at the Control Area which Permits Surveillance of All Ports and Doors During X-Ray Generation			☑ YES	☐ NO
	Means Provided to the Operator for Terminating Exposures of Greater Than One-Half Second and Preventing Additional Exposures of Less Than One-Half Second			☑ YES	☐ NO

SEMI PM
WO 3738879
EQ 57356
DEN

Form # 002.SerFRSSHF
Revision Date 03/11/2008

Smiths Detection

Field Radiation Survey Sheet

SECTION	PART II - SPECIFIC PROCEDURE INFORMATION
H "LEAKAGE RADIATION"	LEAKAGE RADIATION - SPECIFIC TEST PROCEDURE # 01

Scattering Body Description: 8 rems — ☐ Lucite ☑ Paper ☐ Other — Describe Other:

X-Ray Machine Settings: See Comments — kV: Sec I — mA: Sec I

Radiation Survey Instrument Used — Make/Model Number: Envision 451P — Serial Number: 475 — Calibration Date Due: 9/16/11

Background: 8 uR/hr

Survey Location Description	Survey Point	External Surface Exposure Rates (uR/hr)		Internal Exposure (mR) "Optional"		Comments
Ent. Tunnel	1	23	uR/hr		mR	
PAX Ent. End	2	14	uR/hr		mR	
OPER Ent. End	3	23	uR/hr		mR	
Exit Tunnel	4	41	uR/hr		mR	
PAX Exit End	5	24	uR/hr		mR	
OPER Exit End	6	21	uR/hr		mR	
OPER Small	7	20	uR/hr		mR	
OPER Center	8	23	uR/hr		mR	
OPER Large	9	17	uR/hr		mR	
PAX Small	10	22	uR/hr		mR	
PAX Center	11	19	uR/hr		mR	
PAX Large	12	19	uR/hr		mR	
Top	13	17	uR/hr		mR	

Highest External Surface Exposure Rate Reading: 41 uR/hr — Location Description: #4

All External Surface Exposure Rate Readings Are Less Than 500 uR/hr (0.5 mR/hr) IAW 21 CFR 1020.40: ☑ YES ☐ NO

I "ADDITIONAL INFORMATION"	ADDITIONAL INFORMATION				
	Overall Condition of Cabinet X-Ray Unit	☑ SAT	☐ UNSAT *	* Describe UNSAT Condition	
	Condition of Lead Curtains	☑ SAT	☐ UNSAT *	* Describe UNSAT Condition	

Other Comments, Recommendations, Corrections, or Problems Encountered

	KV	mA
A	165	526
B	157	480
C	162	503
D	159	485

Average Internal Dose .77 mRem/hour

[redacted] 3-16-11

Section G - No Doors/Interlocks Applicable

SURVEYOR'S NAME (Print: Last, First, Middle Int.): [redacted]

SURVEYOR'S SIGNATURE: [redacted]

DATE OF SURVEY AND INSPECTION: 3/9/11